



- D101 ~ 105 IS2473
- D106, 107 20A90
- D109 TLR-114
- D110, 111 IS2473

- TR105 2SC-1096L
- D108 F14A
- D112 RD13EB

TEST POINT
TP102 (76KHz)

SIGNAL
STRENGTH
METER

STEREO
INDICATOR

TUNING
METER

POWER SW

AC 220V
50Hz

OUT PUT

RCH

LCH

IC101 HA-11211

IC102 HA-1196

1/2 IC101

IC102

MUTING

FM

AM

SIGNAL
STRENGTH
METER

STEREO
INDICATOR

TUNING
METER

POWER SW

AC 220V
50Hz

OUT PUT

RCH

LCH



