

Region Setting

The above models are delivered factory set to either R1 or R2 depending on the version. To change the region code to your own area please perform the following,

- 1. Turn on the unit and remove any discs .*
- 2. Press the “Pause” button on the remote control.*
- 3. Press numeric buttons: 3 1 4 1 5 9*
- 4. VFL shows ‘CODE--‘*
- *5. Enter the code for your region and press “Pause” button again.*
- 6. Turn off power.*

** NOTE: Perform step 5 as quick as possible for unit to accept command.*

This completes the region setting.

Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.NADelectronics.com

Region Setting

The above models are delivered factory set to either R1 or R2 depending on the version. To change the region code to your own area please perform the following,

- 1. Turn on the unit and remove any discs .*
 - 2. Press the “Pause” button on the remote control.*
 - 3. Press numeric buttons: 3 1 4 1 5 9*
 - 4. VFL shows ‘CODE--‘*
 - *5. Enter the code for your region and press “Pause” button again.*
 - 6. Turn off power.*
- * NOTE: Perform step 5 as quick as possible for unit to accept command.*

This completes the region setting.

Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.NADelectronics.com

Software Upgrade

***PROBLEM1:** When loading Disney's Atlantis you can't escape from the Main Menu . When playing Star Wars-Episode 1 alien language appears .*

***PROBLEM2:** When playing cd's with music that starts at time 00:00 on the first track you may notice the first ½ second of music is muted.*

***CAUSE1:** The current software doesn't recognize the dvd 's menu system.*

***CAUSE2:** The software is muting this part of the cd track.*

***SOLUTION:** Upgrade the software with software upgrade Version 0312.This upgrade solves both problems. The software is available from our service website to download to a CD-R. Follow the instructions for upgrading from the upgrade procedure provided.*

PRODUCTION:

This change has been implemented in production from serial number: L23T57103851

Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com