

If you choose to buy a \$400 receiver, here are some choices.

	Power output continuous (RMS) watts per channel, both channels driven into 8 ohms	Power output continuous (RMS) watts per channel, both channels driven into 4 ohms	Harmonic distortion a rated output, %	IHF power bandwidth	IHF sensitivity, μ V	FM signal to noise ratio, dB	FM distortion, %	Capture ratio, dB	Spurious response rejection, dB	Manufacturer's suggested retail price
Fisher 450 T	55	NA	0.5	10Hz to 30kHz	2.0	65	0.5	2.5	90	\$399.95
Kenwood KR 6160	55	65	0.5	12Hz to 30kHz	1.6	68	0.5	1.5	100	\$429.95
Marantz 2245	45	NA	0.3	7Hz to 70kHz	2.3	NA	0.15	1.6	95	\$449.95
McIntosh 1700	40	40	0.25	NA	2.5	65	0.5	2.0	NA	\$599.00
Pioneer SX 828	60	75	0.5	10Hz to 60kHz	1.7	70	0.2	1.5	100	\$429.95
Sansui 5000 X	55	75	0.8	15Hz to 30kHz	1.8	65	0.5	1.5	95	\$429.95
Scott 477	70	100	0.5	15Hz to 40kHz	1.9	70	0.5	2.5	80	\$399.90
Sony 6065	70	80	0.2	50Hz to 30kHz	2.2	70	0.2	1.5	100	\$410.00

These data were obtained from manufacturers' literature.

(Scott 477 is your best choice.)

As an astute audiophile, you naturally want to compare specifications and prices on the better makes of equipment before committing yourself. If it's a high quality receiver you're after, we've aided your selection by preparing a spec chart comparing our 477 AM-FM Stereo Receiver with its closest competitors.

We invite you to study the specifications of the

respective units along with their prices. You'll find the Scott 477 is the value-for-the-price leader among this distinguished grouping of receivers in the \$400 price class.

If you're not convinced by specs alone, we further invite you to ask your Scott dealer for a listening test of the 477 receiver connected to your favorite speaker system. Check its performance on both recorded and broadcast program material of your choice. Then, compare the 477 with any other receiver in its price class.

You'll find the Scott 477 AM-FM Stereo Receiver is your best choice.



SCOTT[®]
where innovation is a tradition

H.H. Scott, Inc., 111 Powdermill Road, Maynard, Mass. 01754

Check No. 100 on Reader Service Card