



BEDIENTEILPLATTE




NOTES:
 ⚠ COMPONENTS DESIGNATED BY THE SAFETY SYMBOL SHOULD WHEN NECESSARY FOR REPAIR BE REPLACED BY ORIGINAL PARTS, PRODUCED AND PROVED BY THE MANUFACTURER. ONLY THEN CAN THE OPERATIONAL SAFETY BE GUARANTEED.


KOPFHORERPLATTE





TEST-SCHALTUNG




HAUPTLEITERPLATTE



Odtwarzacz CD
Telefunken HS895CD
 (strona 1/2)




BEDIENTEILPLATTE




NOTES:


⚠ COMPONENTS DESIGNATED BY THE SAFETY SYMBOL SHOULD WHEN NECESSARY FOR REPAIR BE REPLACED BY ORIGINAL PARTS, PRODUCED AND PROVED BY THE MANUFACTURER. ONLY THEN CAN THE OPERATIONAL SAFETY BE GUARANTEED.




KOPFHORERPLATTE




TEST-SCHALTUNG





HAUPTLEITERPLATTE






Odtwarzacz CD
Telefunken HS895CD
 (strona 1/2)








HAUPTLEITERPLATTE









Odtwarzacz CD Telefunken HS895CD
(strona 2/2)